

VEHICLE INSPECTION REPORT

SG13OEO

Peugeot Bipper 1.3 HDi 75 S

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Location Livingston

Reg. date 22/03/2013

Year 2013

Mileage 74,920 Miles
Warranted

Fuel Type DIESEL

GVW 1750kg

Colour BLUE

VIN VF3AAFHZ0D8375337

Body Style Panel Van SWB

MOT Due 11/08/2027

CAP Clean £640.00

CAP Average £490.00

CAP Below £330.00

Gearbox MANUAL

Gears 5

SIDE LOAD DOOR.

Tyres

NSF

NSR

OSF

OSR

Spare

Features


- Rear parking sensor
- Radio/CD
- Central locking

Photos





Condition Check



Damage Photos



1: Sill os
Rusted
Over 5mm

2: Bonnet
Dented
With Paint Damage



3: Wing osf
Rusted
Over 5mm

4: Door osf
Dented
Over 30mm



5: Sill os
Poor Previous Repair
Paint Flake

6: Tailgate
Dented
With Paint Damage



7: Door nsr
Dented
With Paint Damage

8: Door nsf
Dented
Over 30mm



9: Sill ns
 Poor Previous Repair
 Poor Paint

10: Wing nsf
 Rusted
 Over 5mm

Interior

Carpet Condition		Upholstery Condition	
Seat Condition		Odour	
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK