

VEHICLE INSPECTION REPORT

DG17KUH

Daf CF 330

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date	26/05/2017	VIN	XLRASM4100G156597	Rear Suspension	Air
Year	2017	Body Style	Fridge Box	Rear Doors	Roller
Mileage	572,088 Km Warranted	Cab Type	SLEEPER CAB	Tail Lift	Tuckaway
Fuel Type	Diesel	Gearbox	AUTOMATIC		
Colour	WHITE	Axle Combi	6x2		

WARNING LIGHTS ON DASH CARRIER SUPRA 1150 MT UNIT, STANDBY PLUG.


Tyres


NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Park assist camera
- Radio/CD
- Air conditioning


Photos







Condition Check



Damage Photos



1: Seat Base Cover osf
Torn
Over 3mm



2: Carpets Front
Torn
Over 10mm



3: Door Moulding osf
Scuffed (Unpainted)
Over 100mm



4: Bonnet
Chipped
Multiple Chips



5: Bumper Front
Rusted
Over 5mm



6: Qtr Panel osr
Dented
Over 30mm



7: Qtr Panel nsr
Dented
Over 30mm



8: Door osf
Rusted
Over 5mm



9: Door Moulding nsf
Scuffed (Unpainted)
Over 100mm

Interior

Carpet Condition		Average		Upholstery Condition		Average	
Seat Condition		Average		Odour		-	
Engine Runs	OK			Gearbox 1st and Reverse Test	OK		
Brakes	OK			Clutch Slip Test from Static	OK		
Turbo Boosting	OK			Gearbox Static Gear Selection (engine running)	OK		
Parking Brake	OK			No Excessive Smoking	OK		
EML light illuminated	Fault			Oil warning light illuminated	OK		
Airbag light illuminated	OK			DPF light illuminated	OK		
ABS light illuminated	Fault			Service indicator light illuminated	OK		
Windows	OK			Radio	OK		
				Steering	OK		