

VEHICLE INSPECTION REPORT

CN69VXM

Mercedes-Benz Sprinter 314 CDI

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date 24/09/2019

Year 2019

Mileage 146,708 Miles
Warranted

Fuel Type Diesel

Colour WHITE

VIN WDB9106332P135149

Body Style Panel Van MWB

MOT Due Expired

CAP Clean £8,425.00

CAP Average £7,425.00

CAP Below £5,900.00

Gearbox MANUAL

AD BLUE, SIDE LOAD DOOR.

Tyres

NSF

NSR

OSF


OSR

Spare

Features


- Radio/CD
- Front electric windows
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Dented
Over 30mm



2: Bumper Front Moulding
Broken
Replace



3: Wing nsf
Dented
With Paint Damage



4: Door osf
Dented
Over 30mm



5: Qtr Panel osr
Dented
With Paint Damage



6: Bumper Rear Moulding
Broken
Replace



7: Qtr Panel nsr
Dented
With Paint Damage



8: Door nsr
Dented
Over 30mm

Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		No
Engine Runs		OK	Gearbox 1st and Reverse Test		OK
Brakes		OK	Clutch Slip Test from Static		OK
Turbo Boosting		OK	Gearbox Static Gear Selection (engine running)		OK
Parking Brake		OK	No Excessive Smoking		OK
EML light illuminated		OK	Oil warning light illuminated		OK
Airbag light illuminated		OK	DPF light illuminated		OK
ABS light illuminated		OK	Service indicator light illuminated		OK
Windows		OK	Radio		OK
			Steering		OK