

VEHICLE INSPECTION REPORT

YR68ULM

Ford Ranger XL 2.2 TDCi

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Present
		Cap Id	34994
		Cap Code	FORA22RXL PDTM4 5 L

Details

Location	Doncaster	Colour	RED	CAP Below	£5,275.00
Reg. date	19/10/2018	VIN	6FPNXXMJ2NJU07304	Gearbox	MANUAL
Year	2018	Body Style	Panel Van LWB	Gears	6
Mileage	28,386 Miles Warranted	MOT Due	10/04/2027	Axle Combi	4x4
Fuel Type	DIESEL	CAP Clean	£8,175.00		
GVW	3200kg	CAP Average	£6,950.00		

AD-BLUE

Tyres

NSF

NSR

OSF

OSR



Spare

Features

- Bluetooth connection
- Auxiliary input socket
- Digital radio
- Front electric windows
- Drivers airbag
- Passenger airbag
- Central locking
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Cracked
Over 25mm



3: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm



4: Door nsf
Scratched
Over 25mm Not Thru Paint



5: Door nsf
Chipped
Edge Chip



6: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



7: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



8: Qtr Panel nsr
Dented
With Paint Damage



9: Door Mirror Assy osf
Scuffed (Unpainted)
UpTo 100mm

Interior

Carpet Condition	-	Upholstery Condition	-
Seat Condition	-	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		