

# VEHICLE INSPECTION REPORT

**BH19HCK**

## Nissan E-Nv 200 80KW ACENTA 40KWH

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT

V5 Buyer To Apply

### Details

Reg. date 19/08/2019

Year 2019

Mileage 22,494 Miles  
Warranted

Fuel Type Electric

Colour WHITE

VIN VSKYAAME0U0611725

Body Style Panel Van

MOT Due Expired

CAP Clean £4,350.00

CAP Average £3,825.00

CAP Below £3,050.00

Gearbox AUTOMATIC

Gears 1

SIDE LOAD DOOR, E/ MIRRORS, HEATED WINDSCREEN, CHARGING CABLES IN REAR

### Tyres

NSF

NSR

OSF


OSR

Spare

## Features

- Cruise control
- Air conditioning
- Central locking
- Front parking sensor
- Front electric windows
- Cloth seat trim
- Rear parking sensor
- Drivers airbag
- Radio/CD
- Passenger airbag


## Photos







## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
Multiple Chips



2: Door Mirror Assy nsf  
Scuffed (Unpainted)  
UpTo 100mm





3: Door osr  
Dented  
Over 30mm



4: Qtr Panel osr  
Dented  
Over 30mm



5: Screen Front  
Cracked  
Replace



6: Seat Base Cover osf  
Soiled  
Heavy



7: Seat Base Cover nsf  
Soiled  
Heavy



8: Dash Warning Lights  
Displayed  
No Action

## Interior

**Carpet Condition**  
**Seat Condition**

OK  
Poor

**Upholstery Condition**  
**Odour**

OK  
No